Approved For Release 2006/06/27 : CIA-RDP78B04770A001100060014-0				
Contract	25X1			
FY-69 Quarterly Report No. 1 DDR-Dupe				
PAR 249 31 Aug 68				
SUBJECT: Precision Enlarger Prototype (BPE) Operational Improvements and Maintenance	25X1			
TASK/PROBLEM				
1. Provide photographic enlarger maintenance at the customer's				
facility for one Precision Enlarger (BPE) and three 10-20-40X	25X1			
Enlargers.*				
DISCUSSION				
2. Contractor personnel visited the customer's facility twice				
during the report period and while there performed the following				
maintenance effort on the BPE:				
a. On 26 and 27 June 1968:				
(1) Misalignment in the transport system film tracking				
was corrected.				
(2) The X- and Y-coordinate counter system was retrofitted.				

- (3) The X-coordinate counter was found to be out of alignment and was corrected.
- (4) Some of the lights that indicate plus and minus on the Ycounter system were defective and were replaced.
- (5) Brushes that are activated during the drying cycle to remove excess fluid from the bottom side of the film were aligned.

*	The wording of t	his TASK/PROBLEM has t	een changed from the original PAR	
	to reflect the co	ontractor's understand	ing, and the customer's concurrence	∍,
	of the work state	ement (per contractor!	s message 0559 dated 8 August 1968	
	and telecon		on 13 August 1968).	25X1

-8-

PAR 249 31 Aug 68

- b. In the period from 6 through 9 August 1968:
 - (1) The fluorescent bulb in the viewer box was replaced.
- (2) The easel platen was removed and the front and back were cleaned.
 - (3) The lamphouse drive assembly was readjusted.
- (4) The pushbuttons in the sub-control assembly were lubricated.

PLANNED ACTIVITY

3. Perform both the one-month and six-month preventative maintenance checks during the week of 9 September 1968.